

GigaDevice Semiconductor Inc.

Device limitations of GD32E50x

Errata Sheet

Revision 1.6

(Jun. 2025)

Table of Contents

Table of Contents	2
List of Figures	4
List of Tables	5
1. Introduction	6
1.1. Revision identification	6
1.2. Summary of device limitations	6
2. Descriptions of device limitations	9
2.1. PMU	9
2.1.1. Standby mode cannot be waked up due to frequent wakeup signals before or after entering standby mode	9
2.1.2. Power consumption will increase when using LVD detection in standby mode	9
2.2. RCU	9
2.2.1. MCU cannot be waked up from Deepsleep mode when DSLP_HOLD bit is set	9
2.3. GPIO	10
2.3.1. When the OSCIN and OSCOUT pins are remapped to PD0 / PD1 pins, PD0 / PD1 can be used as a normal GPIO function but cannot be used as an EXTI function	10
2.3.2. The square wave or negative voltage on PD5 will affect the stability of core voltage	10
2.4. DAC	10
2.4.1. There is leakage between the DAC output pin and the VREFP pin	10
2.5. TIMER	11
2.5.1. Data lost when using timer capture / compare event to trigger DMA transfer and enabling the output compare shadow function	11
2.6. SHRTIMER	11
2.6.1. In certain cases, DLL calibration will lose SET / RESET	11
2.6.2. Unable to enter fault interrupt	11
2.6.3. SHRTIMER works abnormally when the update source is configured	11
2.6.4. Wave loss occurs when using DLL to multiply frequency of SHRTIMER	12
2.6.5. When using the update event function, there are wave loss, counter abnormal reset, and counter overperiod counting problems	12
2.7. I2C	12
2.7.1. Read one more data because the BTC flag was not cleared	12
2.7.2. When I2C2 works in 7/10 address slave mode, receiving an abnormal timing will cause the SDA line to stuck	13
2.8. SQPI	13
2.8.1. The power consumption in Deep-sleep / Deep-sleep 1 / Deep-sleep 2 mode is high when using	

external PSRAM	13
2.8.2. The power consumption in standby mode is high when using external PSRAM	13
2.9. SDIO	14
2.9.1. In SDIO multi-line mode (4-bit or 8-bit data width), after completing data reception, if the FIFO is not cleared in time and subsequent data arrives on the data line, it will cause the STBITE error to remain set state.....	14
2.10. EXMC	15
2.10.1. NE timing can not satisfy the requirement when using NAND pre-waiting function.....	15
2.11. CAN	15
2.11.1. RS bit is 1 in default.....	15
2.12. ENET	15
2.12.1. The TBU interrupt fails to set the NI state.....	15
2.13. USB	16
2.13.1. When the LPM slave machine is connected to the PC host, if the previous control transaction of the LPM transaction is STALL, the LPM transaction will also be STALL.....	16
2.13.2. Failure of data transfer in high speed synchronous pressure test.....	16
3. Revision history	17

List of Figures

Figure 1-1. Device revision code of GD32E50x.....	6
---	---

List of Tables

Table 1-1. Applicable products	6
Table 1-2. Device limitations	6
Table 3-1. Revision history	17

1. Introduction

This document applies to GD32E50x product series, as shown in [Table 1-1. Applicable products](#). It provides the technical details that need to be paid attention to in the process of using GD32 MCU, as well as solutions to related problems.


Table 1-1. Applicable products

Type	Part Numbers
MCU	GD32E503xx series
	GD32E505xx series
	GD32E507xx series
	GD32E508xx series
	GD32EPRTxx series

1.1. Revision identification

The device revision can be determined by the mark on the top of the package. The 1st code on the line 3 of the mark represents product revision code. As the picture shown in [Figure 1-1. Device revision code of GD32E50x](#).

Figure 1-1. Device revision code of GD32E50x



1.2. Summary of device limitations

The device limitations of GD32E50x are shown in [Table 1-2. Device limitations](#), please refer to section 2 for more details.

Table 1-2. Device limitations

Module	Limitations	Workaround	
		Rev. Code A	Rev. Code B
PMU	<i>Standby mode cannot be waked up due to frequent wakeup signals before or after entering standby mode</i>	N	N
	<i>Power consumption will increase when using LVD detection</i>	Y	Y

Module	Limitations	Workaround	
		Rev. Code A	Rev. Code B
	<i>in standby mode</i>		
RCU	<i>MCU cannot be waked up from Deepsleep mode when DSLP_HOLD bit is set</i>	Y	Y
GPIO	<i>When the OSCIN and OSCOUT pins are remapped to PD0 / PD1 pins, PD0 / PD1 can be used as a normal GPIO function but cannot be used as an EXTI function</i>	Y	--
	<i>The square wave or negative voltage on PD5 will affect the stability of core voltage</i>	Y	Y
DAC	<i>There is leakage between the DAC output pin and the VREFP pin</i>	Y	--
TIMER	<i>Data lost when using timer capture / compare event to trigger DMA transfer and enabling the output compare shadow function</i>	Y	Y
SHRTIMER	<i>In certain cases, DLL calibration will lose SET / RESET</i>	N	--
	<i>Unable to enter fault interrupt</i>	N	--
	<i>SHRTIMER works abnormally when the update source is configured</i>	N	--
	<i>Wave loss occurs when using DLL to multiply frequency of SHRTIMER</i>	N	N
	<i>When using the update event function, there are wave loss, counter abnormal reset, and counter overperiod counting problems</i>	N	--
I2C	<i>Read one more data because the BTC flag was not cleared</i>	Y	Y
	<i>When I2C2 works in 7/10 address slave mode, receiving an abnormal timing will cause the SDA line to stuck</i>	N	N
SQPI	<i>The power consumption in Deep-sleep / Deep-sleep 1 / Deep-sleep 2 mode is high when using external PSRAM</i>	Y	Y
	<i>The power consumption in standby mode is high when using external PSRAM</i>	Y	Y
SDIO	<i>In SDIO multi-line mode (4-bit or 8-bit data width), after completing data reception, if the FIFO is not cleared in time and subsequent data arrives on the data line, it will cause the STBITE error to remain set state</i>	Y	Y
EXMC	<i>NE timing can not satisfy the requirement when using NAND pre-waiting function</i>	Y	Y
CAN	<i>RS bit is 1 in default</i>	N	N
ENET	<i>The TBU interrupt fails to set the NI state</i>	Y	--
USB	<i>When the LPM slave machine is connected to the PC host, if the previous control transaction of the LPM transaction is STALL, the LPM transaction will also be STALL</i>	Y	Y

Module	Limitations	Workaround	
		Rev. Code A	Rev. Code B
	<i>Failure of data transfer in high speed synchronous pressure test</i>	Y	Y

Note:

Y = Limitation present, workaround available

N = Limitation present, no workaround available

'--' = Limitation fixed

2. Descriptions of device limitations

2.1. PMU

2.1.1. Standby mode cannot be waked up due to frequent wakeup signals before or after entering standby mode

Description & impact

When reset the internal signal STBY_CTL to enter to standby mode, if the T_{glitch} is smaller than 100ns, which will cause the MCU cannot be waked up. The narrow glitch will result in incorrect Vcore voltage.

Note: The T_{glitch} is the time between STBY_CTL low level and the wakeup signal (PA0 high level)

Workarounds

Not available.

2.1.2. Power consumption will increase when using LVD detection in standby mode

Description & impact

When the LVD detection function is enabled, the standby power consumption will increase due to LVD detection function cannot be automatically disabled in standby mode.

Workarounds

The application program needs to disable LVD detection before entering standby mode.

2.2. RCU

2.2.1. MCU cannot be waked up from Deepsleep mode when DSLP_HOLD bit is set

Description & impact

When the DSLP_HOLD bit in the DBG_CTL register is set, the MCU cannot be waked up after the MCU enters deepsleep mode.

Workarounds

When the DSLP_HOLD bit is set to enable low power debugging, the application program needs to switch the system clock to IRC8M before entering the deepsleep mode.

2.3. GPIO

2.3.1. When the OSCIN and OSCOUT pins are remapped to PD0 / PD1 pins, PD0 / PD1 can be used as a normal GPIO function but cannot be used as an EXTI function

Description & impact

When the external crystal function is not used and the OSCIN and OSCOUT pins are remapped to PD0 / PD1 pins, the remapped PD0 / PD1 can be used as a normal GPIO function but cannot be used as an EXTI function.

Workarounds

When the OSCIN and OSCOUT pins are remapped to PD0 / PD1 pins, the use of PD0 / PD1 for EXTI functionality is avoided in the application.

2.3.2. The square wave or negative voltage on PD5 will affect the stability of core voltage

Description & impact

Due to the sensitivity of the PD5 pin to interference signals, the square wave or negative voltage (exceeding $V_{SS}-0.3V$) on PD5 will affect the stability of core voltage (1.1V domain).

Workarounds

Avoid input square wave signal or negative voltage (exceeding $V_{SS}-0.3V$) signal on PD5 pin.

2.4. DAC

2.4.1. There is leakage between the DAC output pin and the VREFP pin

Description & impact

When the DAC is disabled and the V_{DD} voltage is 0.7V higher than the V_{REFP} voltage, the DAC output pin (PA4 / PA5) has leakage to VREFP pin.

Workarounds

Ensure that the voltage difference between V_{DD} and V_{REFP} does not exceed 0.7V.

2.5. TIMER

2.5.1. Data lost when using timer capture / compare event to trigger DMA transfer and enabling the output compare shadow function

Description & impact

When using timer capture / compare event to trigger DMA transfer and enabling the output compare shadow function, DMA transfers data 0x00 to TIMEx_CHyCV register which will result in the second data lost after data 0x00.

Workarounds

Use one of the following solutions:

- 1) Do not use data 0x00 in DMA transfer buffer.
- 2) Transfer the second data after the 0x00 twice.
- 3) Use the timer update event to trigger DMA transfer.

2.6. SHRTIMER

2.6.1. In certain cases, DLL calibration will lose SET / RESET

Description & impact

If the SET / RESET event occurs during DLL calibration, the SET / RESET event may be lost and has no effect on the output.

Workarounds

Not available.

2.6.2. Unable to enter fault interrupt

Description & impact

When a fault event from system fault or fault channel occurs, the corresponding interrupt cannot be generated.

Workarounds

Not available.

2.6.3. SHRTIMER works abnormally when the update source is configured

Description & impact

When SHRTIMER shadow registers are enabled, SHRTIMER works abnormally.

Workarounds

Not available.

2.6.4. Wave loss occurs when using DLL to multiply frequency of SHRTIMER**Description & impact**

When using DLL to multiply frequency of SHRTIMER, sampling deviation may occur in the internal frequency multiplier, which results in SHRTIMER wave loss.

Workarounds

Not available.

2.6.5. When using the update event function, there are wave loss, counter abnormal reset, and counter overperiod counting problems**Description & impact**

When the SHRTIMER update event function is used, problems such as wave loss, counter abnormal reset, counter overperiod counting, etc. occur.

Workarounds

Not available.

2.7. I2C**2.7.1. Read one more data because the BTC flag was not cleared****Description & impact**

If an interrupt occurs before reading I2C_DATA register when RBNE flag is set and BTC flag is reset, I2C will read an additional data if BTC flag is set during the interrupt processing because the read data operation can not clear the BTC flag.

Note: This limitation applies to I2C0 / I2C1.

Workarounds

Use one of the following solutions:

- 1) Using interrupt method to read the I2C_DATA register (need higher interrupt priority).
- 2) Using DMA method to read the I2C_DATA register (recommend).

2.7.2. When I2C2 works in 7/10 address slave mode, receiving an abnormal timing will cause the SDA line to stuck

Description & impact

When the I2C is operating as a slave device in 7-bit address mode and the I2C master simulates I2C communication via IO. If the master sends the following sequence, the I2C slave will enter an error state, causing it to malfunction and the SDA line to remain low:

Start + 10-bit Match Head Address + Start + 7-bit Address Read + Wait ACK + Start

When the I2C is operating as a slave device in 10-bit address mode and the I2C master simulates I2C communication via IO. If the master sends the following sequence, the I2C slave will enter an error state, causing it to malfunction and the SDA line to remain low:

Start + 10-bit Mismatch Head Address + Start

or

Start + 10-bit Match Head Address + Wait ACK + 10-bit Mismatch 8-bit Address + Start

Note: This limitation applies to I2C2.

Workarounds

Software periodically checks the status of the SDA line. If SDA is detected to be stuck low, reinitialize the I2C module.

2.8. SQPI

2.8.1. The power consumption in Deep-sleep / Deep-sleep 1 / Deep-sleep 2 mode is high when using external PSRAM

Description & impact

The power consumption in Deep-sleep / Deep-sleep 1 / Deep-sleep 2 mode is high when using external PSRAM.

Workarounds

Before entering Deep-sleep / Deep-sleep 1 / Deep-sleep 2 mode, configure the unused GPIO into analog mode and reinitialize the corresponding GPIO after waking up .

2.8.2. The power consumption in standby mode is high when using external PSRAM

Description & impact

After MCU entered the standby mode, PF6 connected to PSRAM chip selection signal CEN also loses power, resulting in PSRAM could not enter the standby mode.

Workarounds

Switch standby mode to Deep-sleep / Deep-sleep 1 / Deep-sleep 2 mode.

2.9. SDIO

2.9.1. In SDIO multi-line mode (4-bit or 8-bit data width), after completing data reception, if the FIFO is not cleared in time and subsequent data arrives on the data line, it will cause the STBITE error to remain set state

Description & impact

In SDIO multi-line mode (4-bit or 8-bit data width), after completing data reception, if the FIFO is not cleared in time and subsequent data arrives on the data line, it will cause the STBITE error to remain set state.

Workarounds

Use one of the following solutions:

- 1) When using polling mode, software should check both the STBITE flag and the DTEND flag at the same time. The STBITE flag is considered valid only when STBITE is set and DTEND is not set. The reference code is as follows:

```
if ((RESET != sdio_flag_get(SDIO_FLAG_STBITE)) && \
    (RESET == sdio_flag_get(SDIO_FLAG_DTEND))){
    /* user code */
    ....
}
```

- 2) When using interrupt mode, the interrupt function should process the DTEND flag before the STBITE flag, and the interrupt enable bit STBITEIE should be cleared within the code of handling the DTEND flag. The reference code is as follows:

```
void SDIO_IRQHandler(void){
    if((RESET != sdio_flag_get(SDIO_FLAG_DTEND)) && \
        (0U != (SDIO_INTEN & SDIO_INTEN_DTENDIE))){
        sdio_interrupt_disable(SDIO_INT_STBITE);
        /* user code */
        ....
    }
    if((RESET != sdio_flag_get(SDIO_FLAG_STBITE)) && \
        (0U != (SDIO_INTEN & SDIO_INT_STBITEIE))){
        /* user code */
    }
```

```

        ....
    }
}

```

- 3) Instead of using CMD12 to stop the open transmission of data, the multiblock read uses CMD23 to notify the slave device in advance of the number of data blocks to be transmitted. Then when DTEND is set, there will be no more extra data sent to the data line from the slave.

2.10. EXMC

2.10.1. NE timing can not satisfy the requirement when using NAND pre-waiting function

Description & impact

For some EXMC_NCE-sensitive NAND Flash, NE timing can not satisfy the requirement when using NAND pre-waiting function. NE signal keeps the low level when EXMC_INTx is active.

Workarounds

Using general I/O port to simulate the NE timing to finish the NAND reading and writing, NE signal keeps the low level after starting reading or writing.

2.11. CAN

2.11.1. RS bit is 1 in default

Description & impact

When in default or receiving state, RS bit in CAN_STAT register is 1; When in the sending state, the RS bit is cleared to 0.

Workarounds

When using, pay attention to the above logic processing.

2.12. ENET

2.12.1. The TBU interrupt fails to set the NI state

Description & impact

The NI bit in ENET_DMA_STAT register cannot be set by TBU interrupt, which results in no

NI interrupt occurrence.

Workarounds

Polling the TBU bit in ENET_DMA_STAT register to get TBU status.

2.13. USB

2.13.1. When the LPM slave machine is connected to the PC host, if the previous control transaction of the LPM transaction is STALL, the LPM transaction will also be STALL

Description & impact

In the software code, the STALL operation will STALL both the IN and OUT directions of the control endpoint. If the OUT directions of the control endpoint is STALL, the next OUT control transaction will not be properly responded and will directly return to the STALL. However, SETUP transactions can be received normally. LPM transactions do not belong to SETUP transactions. LPM transactions are a special transaction, equivalent to OUT transactions, resulting in that they cannot be ACK normally.

Workarounds

Modify the code according to the USB requirements of different PCs to solve the problem.

2.13.2. Failure of data transfer in high speed synchronous pressure test

Description & impact

During a high-speed synchronous pressure test, the device does not respond to the IN and OUT token packets of the host after a period of time. As a result, data transmission is interrupted.

Note: This limitation applies to USB product certification phase.

Workarounds

Configure external crystal oscillator for high speed synchronous pressure test.

3. Revision history

Table 3-1. Revision history

Revision No.	Description	Date
1.0	Initial Release	Dec.12 2022
1.1	Update note of chapter 1.2	Apr.4 2023
1.2	Add PMU limitation, referring to chapter 2.1.1	Nov.2 2023
1.3	1. Add limitations of Rev. Code B 2. Add RCU / GPIO / DAC / TIMER / I2C / EXMC / CAN / ENET peripherals limitations	Apr.24 2024
1.4	Update GPIO limitation description & impact, referring to chapter 2.3.2	Jun.27 2024
1.5	1. Update the description of GPIO limitation, refer to <u>The square wave or negative voltage on PD5 will affect the stability of core voltage</u> 2. Add I2C limitation, refer to <u>When SDA line interference causes garbled data on the I2C bus, it can lead to a stuck in the I2C2 slave device</u> 3. Update the description of USB limitation, refer to <u>Failure of data transfer in high speed synchronous pressure test</u> 4. Delete SQPI limitation, <u>Misaligned access to PSRAM causes the program to run out of track</u>	Sep.1 2024
1.6	1. Update SHRTIMER workaround of Rev. Code B, refer to <u>Table 1-2. Device limitations</u> 2. Update the description of SHRTIMER limitation, refer to <u>Wave loss occurs when using DLL to multiply frequency of SHRTIMER</u> 3. Add SDIO limitation, refer to <u>In SDIO multi-line mode (4-bit or 8-bit data width), after completing data reception, if the FIFO is not cleared in time and subsequent data arrives on the data line, it will cause the STBITE error to remain set state</u> 4. Update I2C limitations, refer to <u>When I2C2 works in 7/10 address slave mode, receiving an abnormal timing will cause the SDA line to stuck</u>	Jun.25 2025

Important Notice

This document is the property of GigaDevice Semiconductor Inc. and its subsidiaries (the "Company"). This document, including any product of the Company described in this document (the "Product"), is owned by the Company according to the laws of the People's Republic of China and other applicable laws. The Company reserves all rights under such laws and no Intellectual Property Rights are transferred (either wholly or partially) or licensed by the Company (either expressly or impliedly) herein. The names and brands of third party referred thereto (if any) are the property of their respective owner and referred to for identification purposes only.

To the maximum extent permitted by applicable law, the Company makes no representations or warranties of any kind, express or implied, with regard to the merchantability and the fitness for a particular purpose of the Product, nor does the Company assume any liability arising out of the application or use of any Product. Any information provided in this document is provided only for reference purposes. It is the sole responsibility of the user of this document to determine whether the Product is suitable and fit for its applications and products planned, and properly design, program, and test the functionality and safety of its applications and products planned using the Product. The Product is designed, developed, and/or manufactured for ordinary business, industrial, personal, and/or household applications only, and the Product is not designed or intended for use in (i) safety critical applications such as weapons systems, nuclear facilities, atomic energy controller, combustion controller, aeronautic or aerospace applications, traffic signal instruments, pollution control or hazardous substance management; (ii) life-support systems, other medical equipment or systems (including life support equipment and surgical implants); (iii) automotive applications or environments, including but not limited to applications for active and passive safety of automobiles (regardless of front market or aftermarket), for example, EPS, braking, ADAS (camera/fusion), EMS, TCU, BMS, BSG, TPMS, Airbag, Suspension, DMS, ICMS, Domain, ESC, DCDC, e-clutch, advanced-lighting, etc.. Automobile herein means a vehicle propelled by a self-contained motor, engine or the like, such as, without limitation, cars, trucks, motorcycles, electric cars, and other transportation devices; and/or (iv) other uses where the failure of the device or the Product can reasonably be expected to result in personal injury, death, or severe property or environmental damage (collectively "Unintended Uses"). Customers shall take any and all actions to ensure the Product meets the applicable laws and regulations. The Company is not liable for, in whole or in part, and customers shall hereby release the Company as well as its suppliers and/or distributors from, any claim, damage, or other liability arising from or related to all Unintended Uses of the Product. Customers shall indemnify and hold the Company, and its officers, employees, subsidiaries, affiliates as well as its suppliers and/or distributors harmless from and against all claims, costs, damages, and other liabilities, including claims for personal injury or death, arising from or related to any Unintended Uses of the Product.

Information in this document is provided solely in connection with the Product. The Company reserves the right to make changes, corrections, modifications or improvements to this document and the Product described herein at any time without notice. The Company shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. Information in this document supersedes and replaces information previously supplied in any prior versions of this document.